

City of San Jacinto

City Manager Update – December 2019 February 4, 2020

Department Overview

	October 2019	November 2019	December 2019	2019 Totals	2018 Totals
Phone Calls	1232	952	855	11,167	15,897
Counter Visits	796	393	376	6,826	7,197
Total Customer Contacts	2,028	1,345	1,231	17,993	23,094



Planning Division

	December 2019	2019 Totals	2018 Totals
Entitlements Submitted	2	54	51
Projects Approved	4	47	72
Over the Counter (Temporary Use Permit, Special Event Permit, Home Occupation Permit)	5	96	75



Planning Division







Building & Safety Division


	November 2019	December 2019	2019 Totals	2018 Totals
Building Inspections	243	286	3,642	4,356
Permits Issued	61	39	860	930
Permits Applied For	70	51	1,094	1,255
Private Investment	\$2.362	\$1.264	\$33.916M	\$64.255M




Building & Safety Division

New Single-Family Residences

25	2020	
204	2019	
375	2018	
235	2017	
155	2016	
102	2015	
58	2014	
39	2013	
43	2012	
19	2011	
50	2010	



466 = 7 Yrs



■ 2009 ■ 2010 ■ 2011 ■ 2012 ■ 2013 ■ 2014

2015 **2**016 **2**017 **2**018 **2**019 **2**020



*As of February 3, 2020

Richmond American Homes Seasons at Potter Ranch Before & After Model Home








Richmond American Homes Seasons at Potter Ranch Street Improvements, Development Wall, Street Striping





Richmond American Homes - Seasons at Potter Ranch Landscaping, Sidewalk, Curb, Gutter, Street Lights, Turn Lane






Richmond American Homes Temp Occupancy Inspection Models Are Open








Response to Damaged Structure





Commercial Project - Dollar Tree Framing Stage





Code Enforcement Division

	October 2019	Nov 2019	Dec 2019	2019 Totals	2018 Totals	+/(-)
Notice of Violations Issued	697	421	481	7,069	7,081	(12)
Citations Issued	64	86	62	1,068	994	74
Proactive Activities	699	601	612	8,451	8,613	(162)
New Inspections	151	117	132	1,624	1,618	6
Re-check Inspections	602	472	400	6,981	7,078	(97)
Cases Closed	379	345	247	4,564	4,452	112



Tree Maintenance







Graffiti Abatement





Trailer Storage







Removal of Illegal Dumping








Trashcans & Discarded Appliances







DWPPW - Streets








Improved LED lighting installed on the north exterior of City Hall Staff installed an 8X20 concrete slab for a future bus stop on Lake Park Drive

DWPPW - Streets


Removed debris from car accidents and illegal dumping citywide





DWPPW – Storm Water

Storm pipelines cleaned at 7th & Main Street



DWPPW – Storm Water

December Jetting & Debris Report			
Linear Feet Hydro-jetted	5,090 LF		
Debris Removed from Storm pipelines	180 cubic yards		



Vault vacuuming at State Street and Cottonwood Avenue





Catch basin cleaning at State Street and Ramona Expressway



DWPPW – Parks / Graffiti Removal

Month	Locations
Jan 2020	42
2019 Totals	656

















DWPPW – Parks

Staff completed demolition of several pieces of burned and vandalized play equipment at Coventry Acres Park. New equipment bids are underway.





Repainted recycled water equipment as part of the annual audit. There are now five parks using reclaimed water that helps reduce irrigation cost by 25%.

DWPPW – Parks



Repainted the M60 Tank at Druding Park



Replaced 3 lamps at Potter Ranch Park

> Drinking fountain repair at Julian Park





DWPPW - Water

January 2020




Bath Well pump testing using 1200 HP engine

> San Jacinto

Pipe repair on San Jacinto Avenue

M	eter Leaks	40
Met	er Readings	4250
ł	Meters Repaired	15
F	Meter Replaced	8
	or Hangers Distributed	373
	sponded to Dig Alerts	81





Refueled emergency diesel generators from new diesel vehicle fuel cell. Savings: \$80.00 per site/per fuel up.







Replaced fire hydrant hit by a vehicle at Minor St & 7th St

DWPPW – Waste Water



JANUARY 2020

Miles of Sewer Lines Cleaned 5.78

Miles of Sewer Lines Videoed .81 & Inspected





Much needed grinder pumps ready to be installed at the Savory Lift Station










New pump rail system for the grinder pumps Single to 3 phase electrical upgrade improves motor efficiency at Savory Lift Station

DWPPW – Waste Water



Down hole lighting system upgrade for the GAP VAX





Check valve replacement at Cottonwood Lift Station

City Manager's Office

Report on Council Priorities will be delivered at the March 3rd City Council Meeting



